### **CZECH REPUBLIC**

### **CIVIL AVIATION INSPECTORATE**

## **AIRWORTHINESS DIRECTIVE**

Number: CAA - AD - 3 - 025/96

# 1. Description: HOT-AIR BALLOON - TIPPING FRAMES OF BALLOON BASKET - REINFORCEMENT

- 2. Applicable to: all by AEROTECHNIK AB produced hot-air balloons equipped with HB 2 burner.
- 3. Reason for Issuance: broken tipping frame of balloon basket at the burner atttachment has occured on one of the ballons during service.
- 4. Effective date: September 1, 1996.
- 5. Apply until: before next take-off.
- 6. Accomplishment Procedure: inspect tipping frames of balloon basked at the burner attachment on all by AEROTECHNIK AB produced hot-air balloons equipped with HB 2 burner. Weld that joint according to the sketch (see enclosure). Procedure is in accordance with the mandatory service bulletin No: AB 006a issued by AEROTECHNIK CZ, s. r. o. on August 25, 1996. Operators of affected balloons may obtain copies of mandatory service bulletin upon request directly from manufacturer address: AEROTECHNIK CZ, s. r. o.

686 04 Kunovice CZECH REPUBLIC

Tel.: 42 632 549122 Fax: 42 632 549128

#### Remarks:

-Compliance with this AD must be recorded in the appropriate Log Book.

-Address inquiries concerning this AD to: Civil Aviation Inspectorate, Airworthiness Division, Ruzyne Airport, 160 08 Prague 6, Czech Republic, tel:+42 2 324086, fax: +42 2 364112

Date of issue: August 29, 1996

Ing. Jan T O M A N
Director of Airworthiness Division
CAI